



Job Description

Position: Welder
Department: Install
FLSA: Hourly
Reports To: Supervisor

Essential Duties:

- Observe and follow all posted, written, and verbally communicated safety standards and PPE requirements
- Work all assigned days, shifts, and overtime as required and/or scheduled
- Drive chassis in and around the facility
- Using a jib crane, overhead crane, slings, fork truck, and/or manual lifting, move components/products into proper position
- Measure, lay-out, locate components accurately and correctly according to all work orders and/or work instructions
- Cut as needed using a torch, portable plasma cutter, and/or iron worker
- Grind and or buff as needed using an angle grinder
- Clamp and/or tack weld parts to secure in position for welding
- Weld all connections according to drawing and/or work instructions using a MIG welder
- Drill bolt holes as required using a magnetic drill, drill press, and/or floor drill in accordance to all quality standards, work instructions, and work orders
- Install hardware as needed in accordance to all quality standards, work instructions, and work orders
- Install and connect electrical harnesses, components, and/or connections in accordance to all quality standards, work instructions, and work orders
- Install and connect pneumatic hoses and/or valves in accordance to all quality standards, work instructions, and work orders
- Install and connect hydraulic hoses and/or valves in accordance to all quality standards, work instructions, and work orders
- Apply touch-up paint to welded and/or installed components in accordance to all quality standards, work instructions, and work orders
- Inspect all work performed in accordance to all quality standards, work instructions, and work orders
- Perform all work in accordance to all posted, written, and verbally communicated time limits (cycle times)
- Perform all posted, written, and verbally communicated preventive maintenance on equipment
- Perform any and all posted, written, and verbally communicated cleaning functions of the work area, equipment, and/or facility
- Duties are subject to change at any time

Qualifications:

- High school diploma and/or GED equivalent
- 1 year of MIG welding experience and/or demonstrated abilities
- Jib crane and/or overhead crane experience and/or demonstrated abilities
- 1 year of torch and/or portable plasma cutter experience or demonstrated ability
- 1 year of angle grinder experience or demonstrated ability
- Floor drill, drill press, and Magnetic drill experience and/or demonstrated abilities
- Ability to read, understand, and follow work instructions, drawings, and work orders
- Ability to measure and record dimensions using a tape measure
- Ability to lift and move 50 lbs.
- Ability to stand, crouch, or kneel for extended periods of time
- Ability to climb a six-foot step ladder



Environmental Conditions:

- Inside/Outside: 95% inside, 5% outside
- Temperature: Dependent on weather, minimal heating and air conditioning
- Humidity: Dependent on weather
- Noise or Vibration: < 85 db

Hazards:

- Finger/Hand: Cuts, abrasions & burns (PPE: Cotton gloves)
- Foot: Crush & contusion (PPE: metatarsal safety shoes)
- Eye: Foreign objects, flash burn (PPE: Safety glasses, welding hood when exposed)
- Face: Burns, metal fragments (PPE: welding hood or grinding shield when exposed)
- Hearing: Exposure to < 85 db (PPE: hearing protection when exposed)